

| ATA REFERENCE | Model Number | SM | REVISION | REVISION DATE |
|---------------|--------------|-----|----------------|---------------|
| 25-09-44 | 907 | 126 | 0 | 02-Oct-08 |
| 25-10-01 | 005 | 507 | SUPSD BY SM641 | 25-11-28 |
| 25-10-02 | 006 | 510 | 0 | 14-Apr-76 |
| 25-10-03 | 010 | 513 | 3 | 02-Feb-87 |
| 25-10-04 | 008 | 512 | SUPSD BY SM671 | 25-11-56 |
| 25-10-05 | 019 | 514 | SUPSD BY SM665 | 25-11-50 |
| 25-10-06 | 630 | 400 | 1 | 21-Dec-99 |
| 25-10-09 | 020 | 518 | SUPSD BY SM638 | 25-11-25 |
| 25-10-10 | 028 | 519 | SUPSD BY SM658 | 25-11-43 |
| 25-10-11 | 031 | 520 | 5 | 13-Jun-88 |
| 25-10-12 | 029 | 521 | 3 | 30-Nov-83 |
| 25-10-13 | 032 | 522 | 5 | 10-Oct-86 |
| 25-10-14 | 026 | 523 | 3 | 25-Nov-86 |
| 25-10-14 | 039 | 524 | 0 | 21-Feb-80 |
| 25-10-15 | 035 | 525 | SUPSD BY SM664 | 25-11-49 |
| 25-10-16 | 046 | 526 | 1 | 28-Nov-86 |
| 25-10-17 | 049 | 527 | 3 | 22-Oct-86 |
| 25-10-18 | 042 | 528 | 2 | 01-Dec-86 |
| 25-10-19 | 044 | 529 | SUPSD BY SM630 | 25-11-17 |
| 25-10-20 | 045 | 530 | SUPSD BY SM648 | 25-11-33 |
| 25-10-21 | 139 | 577 | SUPSD BY SM644 | 25-11-29 |
| 25-10-22 | 026 | 531 | SUPSD BY SM637 | 25-11-24 |
| 25-10-23 | 059 | 533 | SUPSD BY SM629 | 25-11-16 |
| 25-10-24 | 064 | 534 | SUPSD BY SM621 | 25-11-08 |
| 25-10-25 | 041 | 535 | SUPSD BY SM649 | 25-11-34 |
| 25-10-26 | 058 | 536 | SUPSD BY SM636 | 25-11-23 |
| 25-10-27 | 063 | 537 | SUPSD BY SM661 | 25-11-46 |
| 25-10-28 | 063 | 538 | SUPSD BY SM635 | 25-11-22 |
| 25-10-30 | 066 | 540 | SUPSD BY SM655 | 25-11-40 |
| 25-10-31 | 067 | 541 | SUPSD BY SM656 | 25-11-41 |
| 25-10-32 | 049 | 543 | 8 | 17-Jan-20 |
| 25-10-33 | 049 | 542 | 11 | 17-Jan-20 |
| 25-10-34 | 071 | 544 | SUPSD BY SM599 | 25-10-88 |
| 25-10-35 | 064 | 545 | SUPSD BY SM622 | 25-11-09 |
| 25-10-36 | 009 | 546 | SUPSD BY SM673 | 25-11-58 |
| 25-10-37 | 063 | 547 | SUPSD BY SM634 | 25-11-21 |
| 25-10-38 | 053 | 548 | 5 | 08-Jun-90 |
| 25-10-39 | 061 | 549 | 6 | 23-Sep-13 |
| 25-10-40 | 069 | 550 | 5 | 28-Nov-19 |
| 25-10-42 | 058 | 552 | SUPSD BY SM680 | 25-11-65 |
| 25-10-43 | 079 | 553 | SUPSD BY SM660 | 25-11-45 |
| 25-10-44 | 088 | 554 | SUPSD BY SM616 | 25-11-04 |
| 25-10-45 | 093 | 555 | SUPSD BY SM587 | 25-10-76 |
| 25-10-46 | 094 | 556 | SUPSD BY SM596 | 25-10-85 |
| 25-10-47 | 095 | 557 | SUPSD BY SM593 | 25-10-82 |
| 25-10-48 | 097 | 558 | SUPSD BY SM605 | 25-10-94 |
| 25-10-49 | 098 | 559 | SUPSD BY SM606 | 25-10-95 |

| ATA REFERENCE | Model Number | SM | REVISION | REVISION DATE |
|---------------|--------------|-----|-------------------------|---------------|
| 25-10-51 | 096 | 561 | SUPSD BY SM595 25-10-84 | |
| 25-10-52 | 102 | 562 | SUPSD BY SM626 25-11-13 | |
| 25-10-53 | 103 | 563 | SUPSD BY SM625 25-11-12 | |
| 25-10-54 | 104 | 564 | SUPSD BY SM604 25-10-93 | |
| 25-10-55 | 078 | 565 | 5 | 20-Mar-12 |
| 25-10-56 | 118 | 566 | SUPSD BY SM650 25-11-36 | |
| 25-10-57 | 112 | 567 | SUPSD BY SM611 25-11-01 | |
| 25-10-58 | 107 | 568 | SUPSD BY SM608 25-10-97 | |
| 25-10-59 | 134 | 569 | SUPSD BY SM594 25-10-83 | |
| 25-10-60 | 115 | 570 | 18 | 18-Apr-18 |
| 25-10-65 | 159 | 576 | SUPSD BY SM659 25-11-44 | |
| 25-10-69 | 160 | 580 | 8 | 10-Jan-19 |
| 25-10-70 | 185 | 581 | 2 | 16-Jul-14 |
| 25-10-71 | 186 | 582 | 0 | 01-Jul-91 |
| 25-10-72 | 165 | 583 | SUPSD BY SM628 25-11-15 | |
| 25-10-73 | 188 | 584 | 8 | 23-Mar-17 |
| 25-10-74 | 172 | 585 | 0 | 18-Oct-91 |
| 25-10-76 | 093 | 587 | 35 | 11-Jun-20 |
| 25-10-78 | 210 | 589 | 27 | 23-Jul-20 |
| 25-10-79 | 211 | 590 | 31 | 23-Jul-20 |
| 25-10-80 | 212 | 591 | 15 | 23-Jul-20 |
| 25-10-81 | 213 | 592 | 11 | 21-Jul-14 |
| 25-10-82 | 095 | 593 | 27 | 05-Sep-17 |
| 25-10-83 | 134 | 594 | 15 | 08-Sep-10 |
| 25-10-84 | 096 | 595 | 23 | 29-Apr-20 |
| 25-10-85 | 094 | 596 | 18 | 05-Sep-17 |
| 25-10-86 | 183 | 597 | 6 | 23-Mar-01 |
| 25-10-87 | 201 | 598 | 50 | 17-Aug-20 |
| 25-10-88 | 071 | 599 | 14 | 17-Jul-13 |
| 25-10-89 | 218 | 600 | 16 | 21-Jul-14 |
| 25-10-90 | 217 | 601 | 12 | 19-Sep-14 |
| 25-10-91 | 205 | 602 | 14 | 30-Jul-20 |
| 25-10-92 | 199 | 603 | 4 | 18-Jun-13 |
| 25-10-93 | 104 | 604 | 22 | 05-Sep-17 |
| 25-10-94 | 097 | 605 | 13 | 23-Jul-20 |
| 25-10-95 | 098 | 606 | 22 | 04-Jun-20 |
| 25-10-97 | 107 | 608 | 21 | 23-Jul-20 |
| 25-10-98 | 227 | 609 | 11 | 25-Sep-12 |
| 25-11-01 | 112 | 611 | 16 | 15-Jul-20 |
| 25-11-02 | 226 | 614 | 34 | 26-Feb-20 |
| 25-11-03 | 165 | 615 | 12 | 28-Aug-14 |
| 25-11-04 | 088 | 616 | 19 | 30-Aug-16 |
| 25-11-05 | 183 | 617 | 1 | 28-Feb-11 |
| 25-11-06 | 249 | 618 | 7 | 17-Sep-12 |
| 25-11-07 | 243 | 619 | 13 | 19-Mar-14 |
| 25-11-08 | 064 | 621 | 14 | 11-Jun-20 |
| 25-11-09 | 064 | 622 | 24 | 11-Jun-20 |

| ATA REFERENCE | Model Number | SM | REVISION | REVISION DATE |
|---------------|--------------|-----|----------|---------------|
| 25-11-10 | 254 | 623 | 18 | 02-Sep-17 |
| 25-11-11 | 250 | 624 | 7 | 04-May-10 |
| 25-11-12 | 103 | 625 | 15 | 30-Sep-19 |
| 25-11-13 | 102 | 626 | 25 | 13-Nov-17 |
| 25-11-14 | 244 | 627 | 18 | 09-Nov-12 |
| 25-11-15 | 165 | 628 | 4 | 28-Aug-12 |
| 25-11-16 | 059 | 629 | 8 | 03-Feb-12 |
| 25-11-17 | 044 | 630 | 9 | 02-Oct-19 |
| 25-11-18 | 254 | 631 | 12 | 13-Feb-17 |
| 25-11-19 | 256 | 632 | 10 | 27-Jan-20 |
| 25-11-20 | 272 | 633 | 13 | 23-Aug-18 |
| 25-11-21 | 063 | 634 | 29 | 25-Aug-20 |
| 25-11-22 | 063 | 635 | 27 | 18-Aug-20 |
| 25-11-23 | 058 | 636 | 16 | 30-Aug-19 |
| 25-11-24 | 026 | 637 | 16 | 07-Feb-17 |
| 25-11-25 | 020 | 638 | 2 | 19-Oct-09 |
| 25-11-26 | 258 | 639 | 33 | 09-Jun-20 |
| 25-11-27 | 142 | 640 | 9 | 13-Apr-12 |
| 25-11-28 | 005 | 641 | 1 | 21-Jun-01 |
| 25-11-29 | 041 | 644 | 16 | 22-May-15 |
| 25-11-30 | 275 | 645 | 5 | 16-Jan-12 |
| 25-11-31 | 185 | 646 | 11 | 02-Mar-20 |
| 25-11-32 | 209 | 647 | 9 | 23-Jul-20 |
| 25-11-33 | 045 | 648 | 4 | 04-Dec-09 |
| 25-11-34 | 041 | 649 | 7 | 02-Mar-18 |
| 25-11-35 | 255 | 651 | 5 | 26-Sep-12 |
| 25-11-36 | 118 | 650 | 11 | 16-Apr-20 |
| 25-11-37 | 254 | 652 | 18 | 18-Oct-17 |
| 25-11-38 | 258 | 653 | 46 | 07-Sep-20 |
| 25-11-39 | 296 | 654 | 36 | 06-May-20 |
| 25-11-40 | 066 | 655 | 18 | 13-Jan-17 |
| 25-11-41 | 067 | 656 | 18 | 02-Sep-20 |
| 25-11-42 | 307 | 657 | 3 | 04-Sep-12 |
| 25-11-43 | 028 | 658 | 4 | 05-Jul-06 |
| 25-11-44 | 159 | 659 | 3 | 06-Dec-13 |
| 25-11-45 | 079 | 660 | 10 | 23-Jun-17 |
| 25-11-46 | 063 | 661 | 16 | 25-Aug-20 |
| 25-11-47 | 316 | 662 | 2 | 21-Apr-05 |
| 25-11-48 | 317 | 663 | 18 | 24-May-18 |
| 25-11-49 | 035 | 664 | 4 | 22-Oct-10 |
| 25-11-50 | 019 | 665 | 3 | 06-Oct-09 |
| 25-11-51 | 020 | 666 | 2 | 13-Apr-12 |
| 25-11-52 | 318 | 667 | 11 | 13-Oct-17 |
| 25-11-53 | 326 | 668 | 22 | 17-Aug-20 |
| 25-11-54 | 327 | 669 | 21 | 08-May-19 |
| 25-11-55 | 254 | 670 | 15 | 02-Sep-16 |
| 25-11-56 | 008 | 671 | 4 | 20-Jul-12 |

| ATA REFERENCE | Model Number | SM | REVISION | REVISION DATE |
|---------------|--------------|-----|--|---------------|
| 25-11-57 | 390 | 672 | 2 | 01-Dec-15 |
| 25-11-58 | 009 | 673 | 5 | 06-Oct-17 |
| 25-11-62 | 341 | 677 | 14 | 17-May-18 |
| 25-11-65 | 058 | 680 | 1 | 23-Apr-10 |
| 25-11-66 | 318 | 681 | 18 | 03-Aug-18 |
| 25-11-67 | 026 | 682 | 6 | 31-May-16 |
| 25-11-68 | 254 | 683 | 8 | 02-Sep-16 |
| 25-11-69 | 380 | 684 | 34 | 15-May-20 |
| 25-11-70 | 383 | 685 | 28 | 04-Jun-20 |
| 25-11-71 | 384 | 686 | 11 | 26-Apr-19 |
| 25-11-72 | 386 | 687 | 12 | 11-May-18 |
| 25-11-73 | 382 | 688 | 10 | 27-Apr-18 |
| 25-11-74 | 424 | 689 | 11 | 25-Jul-16 |
| 25-11-75 | 441 | 690 | 14 | 21-Jan-20 |
| 25-11-77 | 444 | 692 | 26 | 11-Nov-19 |
| 25-11-78 | 275 | 693 | 1 | 20-Jan-12 |
| 25-11-79 | 449 | 694 | 16 | 09-Mar-20 |
| 25-11-81 | 458 | 697 | 18 | 20-Dec-19 |
| 25-11-82 | 453 | 698 | SUPSD BY SM1031 25-20-24 TO SM1032 25-21-07 25-20-35 | |
| 25-11-83 | 469 | 699 | 7 | 06-Sep-19 |
| 25-11-84 | 470 | 700 | 5 | 16-Feb-18 |
| 25-11-85 | 188 | 701 | 1 | 23-Mar-17 |
| 25-11-86 | 318 | 702 | 5 | 30-Jun-20 |
| 25-11-88 | 469 | 704 | 8 | 28-Feb-20 |
| 25-11-89 | 470 | 705 | 1 | 27-Jun-19 |
| 25-11-90 | 063 | 706 | 3 | 22-Apr-20 |
| 25-11-91 | 318 | 707 | 2 | 13-May-20 |
| 25-11-92 | 482 | 708 | 6 | 15-Aug-20 |
| 25-14-01 | 612 | 401 | 4 | 04-Mar-97 |
| 25-14-02 | 612 | 402 | 3 | 15-May-96 |
| 25-20-01 | 626 | 403 | 2-01 | 16-Oct-98 |
| 25-20-02 | 626 | 404 | 2 | 21-May-98 |
| 25-20-03 | 638 | 405 | 1 | 16-Feb-00 |
| 25-20-04 | 638 | 406 | 1 | 16-Feb-02 |
| 25-20-04 | 204/205/304 | 101 | 3 | 23-Sep-02 |
| 25-20-05 | 639 | 407 | 1 | 16-Feb-00 |
| 25-20-06 | 628 | 408 | 1 | 04-Aug-00 |
| 25-20-07 | 668 | 409 | 1 | 20-Dec-00 |
| 25-20-08 | 670 | 410 | 3 | 20-Jun-03 |
| 25-20-09 | 665 | 411 | 3 | 01-Jan-03 |
| 25-20-10 | 667 | 412 | 3 | 01-Jan-03 |
| 25-20-11 | 666 | 413 | 6 | 21-Feb-07 |
| 25-20-12 | 830 | 414 | 0 | 30-Apr-03 |
| 25-20-13 | 710 | 415 | 1 | 06-May-04 |
| 25-20-14 | 711 | 416 | 2 | 07-Mar-05 |
| 25-20-15 | 770 | 417 | 2 | 27-Jan-20 |

| ATA REFERENCE | Model Number | SM | REVISION | REVISION DATE |
|---------------|-------------------|------|--------------------------|---------------|
| 25-20-16 | 718 | 418 | 1 | 26-Jan-06 |
| 25-20-17 | 728 | 419 | 3 | 28-Jun-07 |
| 25-20-17 | 204CR/205CR/304CR | 102 | 9 | 14-Nov-19 |
| 25-20-18 | 666 | 420 | 1 | 12-Jan-07 |
| 25-20-19 | 805 | 1026 | 1 | 28-Apr-16 |
| 25-20-20 | 805 | 1027 | 0 | 17-Apr-14 |
| 25-20-21 | 471 | 1028 | 0 | 15-Dec-15 |
| 25-20-22 | 471 | 1029 | 9 | 22-Apr-20 |
| 25-20-23 | 471 | 1030 | 9 | 22-Apr-20 |
| 25-20-24 | 453 | 1031 | 1 | 28-Feb-20 |
| 25-20-25 | 453 | 1032 | 1 | 25-Sep-18 |
| 25-20-26 | 453 | 1033 | 2 | 29-Oct-19 |
| 25-20-27 | 453 | 1034 | 1 | 15-Mar-19 |
| 25-20-28 | 453 | 1035 | 2 | 29-Oct-19 |
| 25-20-29 | 453 | 1036 | 0 | 30-Sep-16 |
| 25-20-30 | 453 | 1037 | 0 | 30-Sep-16 |
| 25-20-31 | 453 | 1038 | 1 | 28-Feb-20 |
| 25-20-32 | 453 | 1039 | 0 | 30-Sep-16 |
| 25-20-33 | 453 | 1040 | 0 | 30-Sep-16 |
| 25-20-34 | 453 | 1041 | 1 | 28-Feb-20 |
| 25-20-35 | 453 | 1042 | 0 | 30-Sep-16 |
| 25-20-36 | 453 | 1043 | 1 | 21-Oct-16 |
| 25-20-37 | 477 | 1044 | 9 | 22-Apr-20 |
| 25-20-38 | 453 | 1045 | 1 | 11-May-18 |
| 25-20-39 | 479 | 1046 | 2 | 31-Jan-20 |
| 25-20-40 | 481 | 1047 | 2 | 21-May-20 |
| 25-20-44 | 415 | 1051 | 1 | 10-Feb-20 |
| 25-20-45 | 416 | 1052 | 1 | 10-Feb-20 |
| 25-20-46 | 417 | 1053 | 1 | 10-Feb-20 |
| 25-20-50 | 479 | 1057 | 1 | 15-Aug-20 |
| 25-20-53 | 480 | 1060 | 0 | 29-Jun-20 |
| 25-21-01 | 252 | 642 | 16 | 02-Sep-16 |
| 25-21-02 | 253 | 643 | SUPSD BY SM1005 25-21-07 | |
| 25-21-03 | 303 | 1001 | 2 | 03-Jul-06 |
| 25-21-04 | 334 | 1002 | 31 | 02-Jul-20 |
| 25-21-05 | 325 | 1003 | 9 | 20-Dec-19 |
| 25-21-06 | 348 | 1004 | 6 | 10-Sep-10 |
| 25-21-07 | 253 | 1005 | 5 | 21-Jun-13 |
| 25-21-10 | 427 | 1008 | 2 | 17-Aug-11 |
| 25-21-11 | 394 | 1009 | 5 | 23-Feb-16 |
| 25-21-12 | 403 | 1010 | 12 | 30-Aug-18 |
| 25-21-13 | 398 | 1018 | 4 | 17-Mar-15 |
| 25-21-14 | 409 | 1012 | 2 | 05-Dec-16 |
| 25-21-15 | 407 | 1013 | 7 | 21-Jan-19 |
| 25-21-19 | 400 | 1017 | 11 | 09-Jan-18 |
| 25-21-21 | 350 | 1019 | 1 | 17-Sep-12 |
| 25-21-22 | 408 | 1020 | 0 | 26-Sep-08 |

| ATA REFERENCE | Model Number | SM | REVISION | REVISION DATE |
|---------------|--------------|------|----------|---------------|
| 25-21-23 | 428 | 1021 | 7 | 10-Aug-18 |
| 25-21-24 | 429 | 1022 | 6 | 13-Sep-18 |
| 25-21-26 | 413 | 1024 | 4 | 30-Jul-14 |
| 25-30-01 | 725 | 421 | 1 | 09-Jun-08 |
| 25-30-16 | 65-22-001 | 104 | 0 | 30-Dec-96 |
| 25-31-02 | WB3002 & 909 | 105 | 23 | 19-Feb-20 |
| 25-31-04 | WB3004 | 106 | 1A | 23-Apr-07 |
| 25-31-06 | WB3003 | 107 | 2 | 01-Sep-02 |
| 25-31-07 | WB3005 | 108 | 11 | 26-Nov-19 |
| 25-31-08 | WB2004 | 109 | 1A | 23-Apr-07 |
| 25-31-11 | 906 | 110 | 15 | 08-Jun-20 |
| 25-32-08 | 943 | 150 | 0 | 31-Jul-19 |
| 25-33-01 | 923 | 147 | 0 | 31-Jul-19 |
| 25-33-02 | 908 | 111 | 3 | 21-Apr-15 |
| 25-34-04 | 900 | 112 | 8 | 01-Jun-20 |
| 25-34-15 | 922 | 132 | 3 | 15-Jun-20 |
| 25-34-16 | 922 | 133 | 4 | 15-Jun-20 |
| 25-34-17 | 944 | 148 | 0 | 04-May-18 |
| 25-36-18 | AR2010/12 | 121 | 2 | 16-Oct-98 |
| 25-36-22 | AR2010/12 | 113 | 2 | 19-Oct-98 |
| 25-36-23 | AR3008 | 114 | 2 | 01-Jul-08 |
| 25-36-25 | AR3021/22 | 115 | 5 | 04-Feb-08 |
| 25-36-36 | AR2020 | 127 | 0 | 01-Oct-02 |
| 25-36-40 | AR3008 | 116 | 3 | 16-Jun-08 |
| 25-36-42 | AR3020 | 117 | 4 | 12-Feb-20 |
| 25-36-43 | 902 | 118 | 3 | 21-Jul-07 |
| 25-36-44 | 907 | 119 | 21 | 14-Jul-20 |
| 25-36-45 | 907 | 120 | 0 | 04-Jul-08 |
| 25-36-47 | AR3008 | 128 | 2 | 01-May-15 |
| 25-36-48 | 919 | 129 | 15 | 17-Jan-20 |
| 25-36-49 | 921 | 131 | 10 | 09-Jun-20 |
| 25-36-50 | 928 | 122 | 1 | 25-Feb-19 |
| 25-36-51 | 945 | 149 | 0 | 28-Feb-19 |
| 25-36-52 | 945 | 153 | 0 | 30-Apr-20 |
| 25-37-01 | 916 | 135 | 14 | 07-Nov-19 |
| 25-37-02 | 932 | 151 | 7 | 12-Mar-20 |
| 25-37-03 | 933 | 152 | 0 | 31-Mar-20 |
| 25-40-01 | 724 | 422 | 1 | 17-Mar-08 |
| 25-40-20 | 805 | 300 | 0 | 17-Apr-14 |
| 25-50-01 | 613 | 423 | 5 | 12-Dec-19 |
| 25-50-03 | 631 | 425 | 1 | 21-Dec-99 |
| 25-50-04 | 702 | 426 | 1 | 08-Sep-04 |
| 25-50-05 | 716 | 427 | 2 | 13-Jan-20 |
| 25-50-06 | 729 | 428 | 1 | 07-Apr-08 |
| 53-00-01 | 470 | 900 | 2 | 06-Dec-17 |
| 53-00-02 | 477 | 477 | 1 | 29-Nov-17 |
| 53-01-01 | 201/258 | 613 | 6 | 07-Jul-20 |

| ATA REFERENCE | Model Number | SM | REVISION | REVISION DATE |
|---------------|-----------------------------|------|----------|---------------|
| 53-01-02 | 019/093/059/096/226/296 | 620 | 12 | 15-May-18 |
| 53-01-03 | 104/107/112/211/212/254/258 | 1011 | 3 | 16-Jan-13 |
| 53-01-04 | 380/383/384 | 696 | 2 | 30-Sep-19 |